




The BAE72-S is a duct mounted thermal fuse with local test switch, this safety fuse comes pre-wired to the Belimo BF-T or BLF-T range of fire/smoke spring return damper actuators (Note:- some BAE units are fitted with a green indication LED).



If any of the internal thermal fuses blow in the BAE72-S, it is possible just to replace the fuse part with the service replacement fuse section ZBAE72.

To replace the fuse section it is first recommended that the power to the unit be isolated.

Once isolated remove the BAE72-S from the ductwork and unclip the black fuse section.

Then clip in the new ZBAE72 fuse section and re-install the repaired BAE72-S back in the ductwork.

Finally ensure that the complete actuator is fully tested locally, and from the automated fire system.

Note:- You do not need to replace the complete BAE72-S, only the fuse section.



ZBAE72

Replacement tripping device to BAE
Duct inside temperature 72 °C (colour black)
Probe length = 65 mm

If you require any technical help with the above please contact MHServices for further information.